


SkillsUSA 2023 Process Plan_3X Milling_State

Part Name: Mill State Competitoin	DRW:	Rev: N/A	Student Name:	Date:
-----------------------------------	------	----------	---------------	-------



Program # O20001	
Operation: First	
WCS: G54	
WCS Location:	Top center of stock
Work Holding	6" Vise
Stock	X4.00, Y2.00, Z1.00
Part location:	XYZ Centered
Notes: Place stock centered in vise. Use parallels or step cut vise jaw to hold .25 of the stock bottom. WCS is at the top center of stock	

Tooling:								
Tool #	Tool Type	Diameter	# of Flutes	Flute Length	Stickout	Holder Type	Starting Chip Load	Max SFM
1	Face Mill	2	5	n/a	n/a	CAT 40 - Shell Mill Arbor	0.0025	3000
2	Bull Endmill .06R	0.5	3	1.25	1.5"	CAT 40 - ER 32	0.003	1000
3	Spot Drill 120Deg	0.5	2	0.500"	2"	CAT 40 - ER 32	0.007	300
4	Cobalt Drill 118Deg	0.201	2	1.750"	2"	CAT 40 - ER 32	0.005	300
5	1/4-20 Tap 2.5 Lead	0.25	1	.750"	2"	CAT 40 - ER 32	0.05	150
6	Ball Endmill	0.25	3	0.5	1.5	CAT 40 - ER 32	0.002	1000
7	Bull Endmill .03R	0.25	3	0.5	1.5"	CAT 40 - ER 32	0.001	1000
8	Chamfer Mill 90Deg	0.25	4	.250"	1.5"	CAT 40 - ER 32	0.0015	1000

Operatoin:	Tool #	Radial DOC	Axial DOC	Notes
Face Part	1	75% Tool Dia	.175 Max/ .03 Fin	Rough and finish to model top
Rough part	2	30% Tool Dia	3X Tool Dia Max	Rough Part as needed .010 stock to leave
Finish floor and walls	2	N/A	N/A	Use wear cutter comp
Rough and Finish Slot	7	30% Tool Dia	2X Tool Dia Max	Rough and Finish Slot
Spot drill holes	3	N/A	N/A	
Drill holes	4	N/A	N/A	Peck at 2X dia, Hole depth= 3x Pitch past thread depth
Tap Holes	5	N/A	N/A	Tap full thread past print depth
Chamfer part	8	N/A	N/A	

Student notes:

Judge notes: